




Relates to: R2775N-CSC, R2775NHD-CSC, 4T2775NHD-CSC or 4TU2775N-CSC

Fitted to: Ford Ranger PX and Mazda BT-50 UP & UR

Contact CI: Clutch Industries is Australia's only manufacturer with full Engineering and Test support services. Call us on 1300 369 787 if you require further technical support.

Firm fitment of the clutch disc when placing into the flywheel.

The OE flywheel narrows at opening of this recessed flywheel. When installing the clutch disc into the flywheel the disc needs to be firmly pressed to clear the shoulder. Manual pressure is adequate no tools are needed to assist with this.



Pressure need to be applied to the disc to clear this section of the flywheel

**MAKE SURE PLATE IS
SQUARE AND NOT ON
ANGLE WHEN
INSTALLING**